

Inspection Report

Date: 2020-03-16

Basic Details: MINI EXCAVATOR(UU)

Make	KOMATSU	Model	PC30UU	Serial no.	14047
Year	2007	SMR	5760	Location	Kobe

Specifications:

Boom	Off-set boom	Arm	STD arm	Bucket	STD bucket	Bucket	width(420mm)
Bucket	Capacity(0.08m3)	Blade	Blade	Shoe Type	Rubber shoe	Canopy	Canopy

Other Details:

Frame No.	Yes	Complete Washing	Not applicable (concrete adhered)
-----------	-----	------------------	-----------------------------------

Defect Information

A:New or Rebuilt Unit B:Good with Lapse of Years C:Normal Operation/Appearance of Wear or Quality Down on Lapse
 D:No Problem on Operation, but Repair Requested E:Quick Repair or Replacement requested

No.	Component	Inspected Item	Grade	Defect Information
1	Whole machine	Overall Condition	C	
2	Engine	Condition (start, stop, noise)	C	
		Oil Leak	C	
		Fuel Leak	C	Engine injection pump fuel oozing
		Water Leak	C	
		Engine Blow-By Pressure	C	
		Exhaust Color	C	
		Turbocharger	C	
		Muffler	C	
		Radiator (hydraulic oil/after cooler)	C	
		Engine Oil Cooler	C	
3	Electrical	Alternator	C	
		Starter Motor	C	
		Battery	C	
		Free description	E	Anti-interference system not working
4	Swing	Function	C	
		Overrun	C	
		Swing Machinery	C	
		Swing Circle/Swivel Joint	C	Swivel joint oil oozing
5	Work Unit	Boom	D	Boom foot pin excessive play
		Arm	D	Arm tip deformed
			D	Arm pin excessive play

Basic Details: MINI EXCAVATOR(UU)

Make	KOMATSU	Model	PC30UU	Serial no.	14047
Year	2007	SMR	5760	Location	Kobe

No.	Component	Inspected Item	Grade	Defect Information
5	Work Unit	Bucket (front attachment, etc)	D	Bucket excessive play
			D	Bucket concrete adhered
			D	Side cutter missing
		Blade	C	
		Free description	D	2nd boom pin excessive play
6	Hydraulic	Boom Cylinder	C	Boom cylinder guard deformed
			C	Boom cylinder (right) oil oozing
		Arm Cylinder	C	
		Bucket Cylinder	C	
		Other Cylinders (blade, boom swing, etc)	C	
		Hydraulic Pump	C	
		Control Valve	C	
7	Control	Work Equipment Control Lever/Pedal	C	Travel lever knob (right) broken
			C	Travel lever knob (left) broken
			C	Control lever PPC valve (right) oil oozing
			C	Control lever PPC valve (left) oil oozing
8	Travel (left)	Final Drive (travel motor included)	C	Travel motor cover oil oozing
		Sprocket	D	Sprocket wear
		Shoe (steel, roadliner, rubber pad)	C	
		Rubber Shoe	D	Rubber shoe wear
		Track Link Assembly	C	
		Pin & Bushing	C	
		Idler	C	
		Recoil Cylinder	C	
		Carrier Roller	C	
		Track Roller	C	
9	Travel (right)	Final Drive (travel motor included)	C	Travel motor cover oil oozing
		Sprocket	D	Sprocket wear
		Shoe (steel, roadliner, rubber pad)	C	

Basic Details: MINI EXCAVATOR(UU)

Make	KOMATSU	Model	PC30UU	Serial no.	14047
Year	2007	SMR	5760	Location	Kobe

No.	Component	Inspected Item	Grade	Defect Information
9	Travel (right)	Rubber Shoe	D	Rubber shoe wear
		Track Link Assembly	C	
		Pin & Bushing	C	
		Idler	C	
		Recoil Cylinder	C	
		Carrier Roller	C	
		Track Roller	C	
10	Overall Appearance	Revolving Frame	C	
		Track Frame	C	
		Cab/Canopy	D	Canopy frame deformed
			D	Rear windshield cracked
		Operator's Compartment	C	Seat torn
		Tank/Exterior Cover	C	Counterweight rusted
			C	Side cover (left) deformed
			C	Side cover (right) deformed
			C	Side cover (right) missing
		Paint	C	

Other Defect Information

Grade	Comment
C	Deformed right side hood
D	Rusted track frame
D	Engine hood paint came off
D	Rusted left front frame

Other Machine Information (ATT etc)

Comment
Modified & replaced canopy side windshield (excessive play)
Additional weight mounted