

Inspection Report

Date: 2020-03-09

Basic Details: MINI WHEEL LOADER

Make	MITSUBISHI	Model	WS200L	Serial no.	1W003333
Year	1985	SMR	3449	Location	

Specifications:

Boom	STD boom	Tire (left front)	8.25-R16-14PR	Tire (left front)	Tire groove depth(2mm)	Tire (left rear)	8.25-R16-14PR
Tire (left rear)	Tire groove depth(3mm)	Tire (right front)	8.25-R16-14PR	Tire (right front)	Tire groove depth(3mm)	Tire (right rear)	8.25-R16-14PR
Tire (right rear)	Tire groove depth(4mm)	Bucket	Edge				

Other Details:

Frame No.	Yes	Complete Washing	Not applicable (others)	Paint	Custom color
-----------	-----	------------------	-------------------------	-------	--------------

Defect Information

A:New or Rebuilt Unit B:Good with Lapse of Years C:Normal Operation/Appearance of Wear or Quality Down on Lapse
 D:No Problem on Operation, but Repair Requested E:Quick Repair or Replacement requested

No.	Component	Inspected Item	Grade	Defect Information
1	Overall	Overall Condition	C	
2	Engine	Condition (start, stop, noise)	C	
		Oil Leak	C	Engine head cover oil oozing
		Fuel Leak	C	
		Water Leak	C	
		Engine Blow-By Pressure	C	
		Exhaust Color	C	
		Turbocharger	C	
		Muffler	C	
		Radiator (hydraulic oil, after cooler)	C	
		Engine Oil Cooler	C	
		Free description	D	Oil leak from starter
3	Electrical	Alternator	C	
		Starter Motor	C	
		Battery	C	
4	Transmission/Brake	Torque Converter	C	
		Transmission	C	
		Drive Shaft	C	
		Differential	C	
		Axle (front)	C	
		Axle (rear)	C	

Basic Details: MINI WHEEL LOADER

Make	MITSUBISHI	Model	WS200L	Serial no.	1W003333
Year	1985	SMR	3449	Location	

No.	Component	Inspected Item	Grade	Defect Information
4	Transmission/Brake	Steering Cylinder/Rod (left) (if one piece)	C	
		Brake	C	
5	Work Unit	Boom/Bell Crank	C	
		Bucket Type	C	
		Bucket	C	Bucket cracked
			C	Bucket repair mark
6	Hydraulic	Lift Cylinder/Rod (left)	D	Lift cylinder oil leak
		Lift Cylinder/Rod (right)	C	
		Bucket Cylinder (left) (if one piece)	C	
		Hydraulic Pump	C	
		Control Valve	C	
7	Control	Lever/Positioner	C	
8	Travel	Tire Type	C	
		Tire/Rim (left front)	C	Tire (front left) wear
		Tire/Rim (left rear)	C	Tire (rear left) wear
		Tire/Rim (right front)	C	Tire (front right) wear
		Tire/Rim (right rear)	C	Tire (rear right) wear
9	Overall Appearance	Frame	C	
		Cab/Canopy	C	
		Operator's Compartment	C	Seat torn
		Tank/Exterior Cover	C	Combination lamp broken
			C	Working lamp broken
			C	Working lamp deformed
		Paint	C	
Free description	C	Frame center pin play		

Other Defect Information

Grade	Comment
C	Deformed exhaust pipe
D	Gas leak from engine to radiator

Basic Details: MINI WHEEL LOADER

Make	MITSUBISHI	Model	WS200L	Serial no.	1W003333
Year	1985	SMR	3449	Location	

Other Defect Information

Grade	Comment
E	Broken clutch & gear, Unable to travel forward & reverse
C	No right view mirror, Broken left view mirror

Other Machine Information (ATT etc)

Comment
Shipment by RORO vessel is impossible (unable to travel forward & reverse)